



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
February 4, 2010

Reviewed:

Mine Name: Martin	Permit Number: S/007/0037
Operator Name:	Inspection Date: February 3, 2010
Inspector(s): Wayne Western	Time: 2:00 – 3:00 PM
Other Participants: Chris Conrad (BLM)	Mine Status: SUS

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection do in connection with an inspection of the Italian Tan site.

Inspection Summary:

Do to snow on the ground; visibility at the site was limited. The Operator had stated to the Division that the site had been be seed in December 2009. Therefore, all the requirements for bond release had been completed. Because there is no bond on the site the Division will retire the project.

Conclusions and Recommendations:

The Division should retire the site and close the file.

Inspector's Signature

(whw):pb

cc: (OPERATOR)

Christopher_Conrad@blm.gov

O:\M007-Carbon\S0070037-Martin\inspections\Insp_02042010.doc